

Table 1 - 2014-2017 Road and Highway Projects

Label	Fiscal Year	Project Name	Miles	Work Type	Description
1	2014	M-139, ROW & CON phase	0.1	Bridge replacement	Bridge replacement
2	2014	M-139	0.14	Bridge replacement	Bridge replacement
3	2014	Red Bud Trl-1, Third St-2, Portage Rd-3	6.2	Resurface	Hot mix patching and single seal coat
4	2014	Redfield St	1.27	Restore & rehabilitate	Structural HMA overlay with shoulders and striping
5	2014	Seventeenth St	0.51	Resurface	Resurface
6	2014	Bertrand Rd	1.04	Resurface	Resurface
7	2014	Elkhart Rd	1.33	Resurface	Partial milling and total resurface
8	2015, 2016	US-31 NB	0	Roadside facility	Expand existing lot to add capacity and mill and resurface existing portion of lot
9	2015	Madron Lake-1, N Main-2, Red Bud Trl-3	5.7	Resurface	Hot mix patching and seal coat
10	2015	Range Line Rd-1, Lake St-2, Main St-3	5.1	Resurface	Hot mix patching and seal coat
11	2015	Broadway	0.3	Resurface	Cold Mill and resurface
12	2015	Adamsville	1.5	Restore & Rehabilitate	
13	2016	Galien-Buchanan-1, Bakertown-2, Fourth-3, Terre Coupe-4	5.5	Resurface	Hot mix patching and seal coat
14	2016	Bertrand-1, Third-2, State Line-3	5.1	Resurface	Hot mix patching and seal coat
15	2016	Adamsville St	0.4	Restore & rehabilitate	Crush and shape
16	2016	Red Bud Trail	0.5	Resurface	Cold milling and resurfacing of Red Bud Trail a distance of 2,700', including miscellaneous curb and gutter replacement, ADA sidewalk ramps, misc. subgrade underdrains, sections of full depth pavement replacement and pavement markings. The roadway through this area is experiencing moderate transverse and edge cracking.
17	2016	Fir Rd	1	Resurface	HMA overlay with Shoulders and Striping
18	2016	Fir Rd	0.5	Resurface	HMA Overlay with shoulders and striping
20	2017	Niles-Buchanan-1, Red Bud 2	4.9	Resurface	Hot mix asphalt and seal coat
21	2017	Dayton-1, Orange-2, Third-3, Fulkerson-4, Ontario-5	5.9	Resurface	Hot mix patching and seal coat
22	2016	Sycamore St	0.5	Resurface	Thirteenth Street to Seventeenth Street. Cold mill and resurface
23	2017	Redfield St	1.1	Restore & rehabilitate	Mill and structural overlay with shoulders and stripng